BT-W8 Series

Manual

Power

Adaptor specifications (It is only available to use digital switch ADAPTOR): input 100~240VAC 50~60Hz, output 5.8V/500mA

Chapter One Key Operation

Function	Operation	Introduction
Normal Function	M+	Reference for Chapter Three 3-3 Internal function setting
Setting		It can be set for digital filtering, numerical displaying range,
	Press to switch	starting units, units auto-tare, digital delay and power saving
	on the scale.	standby, etc.
Scale Parameter		Reference for Chapter Three 3-1 Weighing, resolution, decimal
Setting		point setting
	Press Mo and	It can be set for the maximum weighing, resolution and the
	to switch on the scale.	location of decimal point.
Calibration	M+)	Reference for Chapter Three 3-2 The internal weight calibration
	Droop MC and TARE	is for scale's calibration(It is only operated by professional.)
	to envite h on the coole	
	to switch on the scale.	

Button:

(ZERO)

1) Zero

2) When it sets, it can be used as the function of flash point shifts left.



- 1) Deduct the gross weight.
- 2) When it sets, it can be used as the function of reduction of number.

٢	
L	

UNIT

- 1) Unit switch.
- 2) When it sets, it can be used as the increase of number.



1) Display the total accumulated data.

M+ MC

1) To accumulate the weight.

Chapter Two Installation



Load Cell 4 wire type (5 wire type)	Load Cell 6 wire type (7 wire type)
Pin1 connects with EXC+	Pin1 connects with EXC+, SEN+
Pin2 connects with EXC-	Pin2 connects with EXC-,SEN-
Pin3 connects with SIG+	Pin3 connects with SIG+
Pin4 connects with SIG-	Pin4 connects with SIG-
Pin5 connects with Shield	Pin5 connects with Shield

Chaptor Three Internal Data Setting(It is only set by the professional)

3-1 Weighing, Resolution, decimal point setting



MR after setting the data.

Press



It returns to the resolution setting mode; Press

to make sure the whole setting data, and store the data of weighing, resolution, decimal point.

If you need to re-ensure or re set the weighing, resolution and decimal point, you can start with the step 2.

3-2 International Weight Calibration

Press and **TRE** to switch on and warm up the scale in 15~30 minutes to to enable its accurate.



Step 4



It is doing the weight calibrtion.

It means finishing the calibration; Press **Mt** to out of the function.

3-3 Internal Function Setting

Step s	Introduction of functions	Operation	Introduction of operation
Step 1	To start the international function.	Press Mt to switch on the scale.	
		\downarrow	
	Display the operation.	Funštt	
		\downarrow Release the button	
Step 2	digital filtering setting 1, The higher the data, the stronger the filter. 2,The filtering strength is inversely proportional to the speed of scale's response.	0-FZ	Press to set the filter parameters.
		Press Mt	
Step 3	 Numerical display range setting 1, When the weight is smaller than the product by setting d ata times resolution, the scree n of WEIGHT displays 0. e.g. When the weight of object with the resolution is 1g and the setting data is <i>I</i>, the screen of WEIGHT displays 0, or the screen displays the actual weight. 	i - d i	Press to set the num erical display range parame ters. 1- d0 ~ 1- d5 When it is set to be 1- d0 , it is out of the z ero tracing function.
		Press M+	

Step 4	Units Setting 1,When all the units are set t o be closed, the system usually takes "kg' as the unit.	c-u an	Press to select the re quired unit. Press to set if using the related unit. 2^{-u} means usage. 2^{-u} means non-usag e.
		↓ Press M+	
Step 5	Starting Unit Setting 1, Set the starting unit each time.	3-00-0	Press to set the starti ng unit.
		Press Mt	
Step 6	Digital Delay Range Setting 1,When it is stable, weight change is smaller the product setting range by setting data times resolution, the screen displays the weight continuously. e.g. When the weight of the object changes into 1.241kg~ 1.270kg with the stable displaying data is 1.255kg and resolution is 1g, and the setting data is <u>5-HYIS</u> , the screen of weight displays 1.255kg, or it displays actual weight.	<u>5 - H J - 1</u>	Press to set the num erical delay range paramet ers. 5-89-0 5-8915
		Press M+	
Step 7	Power Saving and Standby Setting 1, When the scale's pan is empty and its keypad without any operation for more than 60 seconds, the scale is in the mode of power saving and standby.	<u>3</u> -53no	Press to set the para meters of power saving an d standby.



Put the objects on the pan after selection. Press

5761

to auto-sample after it is stable.

p = 5 expresses the sample number is 5 PCS	P = 100 expresses the sample number is 100 PCS
sample number is 10 PCS	P = 200 expresses the sample number is 200 PCS
P: P: sample number is 20	$p_{2} \rightarrow 50$ expresses the sample number is 250 PCS
expresses the sample number is 50 PCS	
ACCUMUNICATION Press Mt, and the scree mark of accumulation light	en displays to accumulate. At this moment, the s.
Display and Delect the w	veight
When the screen displays condition is wrong.	in accumulation, it expresses the accumulated
Press in accumulati	on, the screen displays the alternate the total accumulated weight
Press in accumulati the accumulated data, and	on display, and the screen displays delecting all delecting all dout of the function.
Press to be out of a Press to display sec	ccumulation display in accumulation. tionally, when the accumulated display is more than 999999.